

Disponibile LASA Metalli profili aperti ferro

Guide superiori

	misura	
omge art.150	14x30	sp.1
omge art. 10	25x19	sp.1
T083	33x34	sp.1,8
T082	43x55	sp.2,5
T081	57x70	sp.3
T050	50x50	sp.2,5
rolling GIPI 4 RPZ	70x60	sp.3,5
rolling GIPI 4 RZ	92x85	sp.4
rolling Wall	75x110	sp.3

Guide inferiori

	misura
T152	int.27
LS32	int.32
rolling art.38	int.42
rolling Floor	x ruota 20
rolling Omega	x ruota 20
rolling art.51	x Omega 2

Ferro a U Zinc.

	2
31x30	Z
35x35	Z
41x40	Z
46x40	Z
56x40	Z

Ferro a L stamp.

	1,5	2	3
20x10	N		
30x20		N	
40x20		N	N
40x30			N
50x20		N	
50x30			N
60x30			N
60x40			N
70x40			N
80x40			N
100x40			N

Ferro a U stamp.

	1,5	2	3	4
10x20	N			
15x20	N			
20x15	N			
25x15	N			
25x40		N		
30x15		D		
30x20		N		
30x40		D		
35x20		D		
40x15	N			
40x20	N	N		
40x30		N		
45x25		N		
50x20	N			
50x25		N		
50x30			N	
50x40			N	
60x20		N		
60x30			N	
60x40			N	
70x40			N	
80x40			N	N
90x40			N	
100x50			N	
120x60			N	
140x60			N	
160x65				N

Ferro a U stamp.

	1,5	2	3	4
10x10	N			
12x12	N			
15x15	N			
20x20	N	N		
25x25	N	N		
30x30		N	N	
35x35		NZ		
40x40		N	N	
50x50		N	N	
60x60			N	

L = Lucido
 D = Decapato
 N = Nero
 Z = Zincato

Ferro a C

	1,5	2
30x15x7,5	D	
30x15x10	D	
30x30x10	D	
40x20x10		N
40x20x12,5		N
40x20x15		N
40x25x12,5		N
40x40x12,5	D	N
40x40x15	D	N
40x40x10		NZ
80x40x20		N

Omega

	2	3
30x25x15	N	
30x50x20	NZ	
40x60x30		NZ
40x80x30		NZ
50x100x30		NZ
60x120x30		NZ

L = Lucido
 D = Decapato
 N = Nero
 Z = Zincato